



Klock Werks FLARE Windshield Care Sheet

⚠ WARNING

Do not clean Lexan® polycarbonate in hot sun or high temperature. Powdered, abrasive or alkaline cleanser will damage the windshield. Never scrape the windshield with a razor blade or other sharp instrument.

⚠ WARNING

Do not use benzene, paint thinner, gasoline or any other type of harsh cleaner on the windshield. Do not use ammonia based solvents or petroleum distillates. Doing so will damage the windshield surface.

⚠ WARNING

Do not use harsh chemicals including rain sheeting products on motorcycle windshields. They can cause a dulling or hazing. To clean day to day road dirt, use a mild soap and warm water with a non abrasive cloth as well as keeping the cloth frequently rinsed in the soapy water. To obtain a proper high-end polish, please use a quality protector and polish such as Plexus® or Novus® brand cleaners.

NOTE: Sunlight reflections off the inside curvature of the windshield can, at certain times of the day, cause extreme heat build-up on motorcycle instruments. Exercise care in parking. Park facing the sun, place an opaque object over the instruments, or adjust the windshield to avoid reflections.